

United States of America  
Department of Transportation — Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA4188SW

*This certificate, issued to* Falcon Jet Corporation  
P.O. Box 967  
Little Rock, Arkansas 72203

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

*Original Product — Type Certificate Number:* A46EU  
*Make:* Dassault-Breguet  
*Model:* Mystere - Falcon 50

*Description of Type Design Change:*

Installation of Radio Master System in accordance with Drawing List Report No. F50-01019, Revision M dated 8/25/86, or later FAA approved revision.

*Limitations and Conditions:*

See Continuation Sheet, page 2 of this STC.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* October 19, 1979

*Date reissued:*

*Date of issuance:* August 26, 1980

*Date amended:* 6/8/82; 2/3/84; 10/16/84; 8/6/86;  
8/25/86 Revision 5

*By direction of the Administrator*



*L. B. Andriesen*  
L. B. Andriesen (Signature)

Manager, Aircraft Certification Division  
Southwest Region (Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

*This certificate may be transferred in accordance with FAR 21.47.*

United States of America  
Department of Transportation—Federal Aviation Administration  
**Supplemental Type Certificate**  
(Continuation Sheet)

*Number* SA4188SEW *Revision* 5

Limitations and Conditions:

Where specific location of "O" Ride and "Radio ON/OFF" switches are specified, FAA Approved Airplane Flight Manual Supplement (Report No. 35087) dated August 26, 1980, is required.

FAA Approved Airplane Flight Manual Supplement (Report No. 35087-1) Revision A dated June 8, 1982, is required. (Specific locations of "O" Ride and "Radio ON/OFF" switches are removed from the supplement.)

FAA Approved Airplane Flight Manual Supplement (Report No. 35087-1) Revision B dated February 2, 1984, is required. (Change "Radio ON/OFF" to read Radio Master and delete "Radio ON/OFF" indication.)

FAA Approved Airplane Flight Manual Supplement (Report No. 35087-1) Revision C dated October 16, 1984, is required. (Bus "B" master O'Ride switch installation.)

FAA Approved Airplane Flight Manual Supplement (Report No. 35087-2) dated August 6, 1986.

Compatibility of this modification with other previously approved modifications must be determined by the installer.

---

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

INSTRUCTIONS: The transfer endorsement below may be used to notify the appropriate FAA Regional Office of the transfer of this Supplemental Type Certificate.

The FAA will reissue the certificate in the name of the transferee and forward it to him.

---

---

## TRANSFER ENDORSEMENT

Transfer the ownership of Supplemental Type Certificate Number \_\_\_\_\_

to *(Name of transferee)* \_\_\_\_\_

*(Address of transferee)* \_\_\_\_\_  
*(Number and street)*

\_\_\_\_\_  
*(City, State, and ZIP code)*

from *(Name of grantor)* *(Print or type)* \_\_\_\_\_

*(Address of grantor)* \_\_\_\_\_  
*(Number and street)*

\_\_\_\_\_  
*(City, State, and ZIP code)*

Extent of Authority (if licensing agreement): \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date of Transfer: \_\_\_\_\_

Signature of grantor *(In ink)*: \_\_\_\_\_